

Reduce Vapourising Cooker & Boiler problems with



If you are an Aga or Rayburn user and have had problems with sooty or hard deposits building up in the base of the burner and oil feed pipes, Oakley's **VBA** (Vapourising Boiler Additive) can help keep your appliance running efficiently.


Oakley's **VBA** is a high-tech additive that has been specially formulated to help vapourising burner owners achieve clean burning and minimise clogging.

Simply adding a 200ml bottle of **VBA** to every 1,000 litres of fuel in your oil storage tank does away with bothersome build-ups in the boiler. And it also combats the sludge that builds in your fuel storage tank, making for all-round fuel efficiency.


Order Oakley's **VBA** now by phoning **01952 684600 (Telford)** or **01827 875588 (Kingsbury)**
www.oakleysueloils.co.uk

Typical vapourising boiler problems...

Soft soot can build and clog these areas




Hard deposits grow in this area between services. They can restrict fuel flow and be difficult to remove



A fuel stability test showed typical heating oil (left) and heating oil after treatment with Oakley's VBA (right)

...And fuel storage tank problems



Over time, particularly during warm summer weather, small oxidation deposits form in ordinary heating oil, sinking to the bottom of the tank and sticking there to create a sludge that can block filters and reduce oil flow. Oakley's **VBA** reduces this problem.

